









Packaging diagram:



RECOMMENDED P.C.B.LAYOUT (TOP VIEW)
TOLERANCE UNSPECIFIED $\pm 0.05\text{mm}$

Note:

1. Send the upper and lower tapes to the tape carrier for adjustment, then put the products into the download tape in the specified way, start the tape winder for winding (Reel/1000pcs), and wrap the upper tape for at least 20cm after winding;
2. Stick the material and RoHS label on the designated position on the surface of each coil of the coil that is OK and put it into the carton. Pack 10tray per carton
3. The carton shall be sealed with sealing tape. The tape shall be I-shaped and shall not cover the label;
4. Stripping force of upper belt: 0.2-1.2N



NINGBO RHT ELECTRONIC CO.,LTD

UNITS:mm

SHEET SIZE: A4

SCALE:---

DRWN BY PAN

USB 3.1 type C Connectors Packaging

0~3

3~18

18~50

50~120

CHK'D BY FENG

THIRD ANGLE PROJECTION


± 0.12

± 0.15

± 0.3

± 0.5

APPR BY ZHAN



RHTAY407